Created 05/01/2011 by Cybernetics Tech Industries

Instructions: Gear Box Repair Kit# CTI-M-0011-DSK

For Gear Motor: 27384-0011 (PS200) – (Gear & Drive Shaft assembly)

- 1. File burs off of output shaft No bumps or burs remain
- 2. Remove the 4 bolts from access plate (opposite shaft)
- 3. Remove access plate Note washer stuck to plate
- 4. Remove shaft and gear assembly Note washers on shaft
- 5. Move snap ring from old shaft to new shaft.
- 6. Move washers from old assemble to new assemble
- 7. Change grease or remove any pieces lost from old gear.
- 8. Install gear shaft
- 9. Fill gear box ~half full of Lithium grease (Mobilith SHC007 worm gear lube)
- 10. Re-install access plate.

Copyright Cybernetics Tech Industries No permission for duplication or publication have been granted